



Ministry of Environment
Inspection Record

Environmental Protection Division

Form containing inspection details: EP System: AMS, Inspection Status: FINAL, System Number: 11678, Inspection No: 17166, EP System Status: Active, Inspection Date: 2014-03-04, Region: Cariboo, Office: Williams Lake, Trigger: Planned, Incidents of Non-Compliance Observed: No, Non-Compliance Decision Matrix Level: Level 0, Non-Compliance Decision Matrix Category: Category 0, Inspector Name(s): Bings, Dan, Risk Ranking: 1 to 2 = Medium, Regulated Party: MOUNT POLLEY MINING CORPORATION, Regulated Party Contact(s): Colleen Hughes, Mailing Address: P.O. BOX 12 LIKELY, BC V0L 1N0, Phone No: (250)790-2215, Fax No: , Contact Email: , Location Description or Site Address: Mount Polley mine - Hazeltine Creek discharge, Latitude: 52.54547 N, Longitude: 121.63433 W, Receiving Environment(s): Surfacewater

Summary

MONITORING AND REPORTING REQUIREMENTS	
Inspection Period: From: 2014-03-04 To: 2014-03-04	
Requirement Source:	
Activity: <u>Office Review</u>	Waste Type: <u>Effluent</u>
Inspection Summary: Annual discharge plan	Response: <u>Notice</u>

Compliance Summary	In	Out	N/A	N/D
Reporting	1	0	0	0

Inspection Details

Requirement Type: <u>Reporting</u>
Requirement Description: Annual discharge plan
Details/Findings: Compliant
Compliance: <u>In</u>

<i>ACTIONS REQUIRED BY REGULATED PARTY and/or ADDITIONAL COMMENTS:</i>	
<i>INSPECTION CONDUCTED BY:</i>	
<i>Signature</i> Dan Bings	<i>Date Signed</i> 2014-03-06
<i>ENCLOSURE(S) TO REGULATED PARTY & DESCRIPTION:</i>	
<u>CVIS Archives</u>	

REGULATORY CONSIDERATIONS:

--

Ministry of Environment	Cariboo Region Environmental Protection Division	Mailing Address: 400-640 Borland St Williams Lake, BC V2G 4T1	Phone: (250) 398-4530 Fax: (250) 398-4214 Website: http://www.gov.bc.ca/env
-------------------------	---	---	---